Prominent fibula

Example 1 | Example 2 | Example 3

Indication	The fibula protrudes laterally. This area causes pain if exposed to pressure. Skin in this area can be prone to recurrent injuries.	
Typical issues	***Off-the-shelf liner is over-stretched on fibula*** To conform with the stump, the standard liner will be stretched out on bony extremities, applying extra-compression on the fibula.	
	Off-the-shelf liner doesn't offer adequate cushioning Off-the-shelf liners inherently provide pre-defined thickness profiles. A liner can present a thick profile to properly protect the fibula, but will thus include unnecessary thicknesses in some areas, leading to heavier liner, risk of additional pistoning and of lowered proprioception. A too-thin liner might not suffer from these limitations, but would on the contrary offer an insufficient cushioning layer, exposing the fibula to pressure peaks, which can lead to pressure sores, and skin injuries.	

©2022 Swiss Motion Technologies SA. All rights reserved.

With Your® Liner

Limb | 3D model | Your® Liner

Key features	**Anatomically tailored**	 **Adjustable thicknesses**
How can Your® Liner help ?	 ***No extra-compression on fibula*** As it's made from a 3D scan, Your® Liner's inner shape can match the protruding fibula shape, thus eliminating the risk of the liner being over-stretched and applying extra-compression on the fibula.	
	Extra cushioning on fibula The possibility of locally applying adequate cushioning allows to apply adequate elastomer thickness to limit the risk of pressure peaks appearing on the fibula. The rest of the liner can present a thin profile to avoid the risks of having a heavier liner, additional pistoning and lowered proprioception.	

©2022 Swiss Motion Technologies SA. All rights reserved.